



SPILL PROCEDURES

Name and telephone number of the person responsible for enforcing safe work practices with nuclear substances in this work area:

Radiation safety officer

Telephone number

24-hour emergency contact

Telephone number

General precautions

1. Inform people in the area that a spill has occurred. Keep them away from the contaminated area.
2. Cover the spill with absorbent material to prevent the spread of contamination.

Minor spills (typically less than 100 exemption quantities of a nuclear substance)

1. Wear protective clothing and disposable gloves, clean up the spill using absorbent paper and place it in a plastic bag for transfer to a labelled waste container.
2. Avoid spreading contamination. Work from the outside of the spill towards the centre.
3. Wipe test or survey for residual contamination as appropriate. Repeat decontamination, if necessary, until contamination monitoring results meet the nuclear substances and radiation devices licence criteria.
4. Check hands, clothing, and shoes for contamination.
5. Report the spill and cleanup to the radiation safety officer or the person in charge.
6. Record spill details and contamination monitoring results. Adjust inventory and waste records appropriately.

Major spill procedures should be implemented whenever minor spill procedures would be inadequate.

Major spills (Major spills involve more than 100 exemption quantities, or significant contamination of personnel, or release of volatile material)

1. Clear the area. Persons not involved in the spill should leave the immediate area. Limit the movement of all personnel who may be contaminated until they are monitored.
2. If the spill occurs in a laboratory, leave the fume hood running to minimize the release of volatile nuclear substances to adjacent rooms and hallways.
3. Close off and secure the spill area to prevent entry. Post warning sign(s).
4. Notify the radiation safety officer or person in charge immediately.
5. The radiation safety officer or person in charge will direct personnel decontamination and will decide about decay or cleanup operations.
6. Decontaminate personnel by removing contaminated clothing and flushing contaminated skin with lukewarm water and mild soap.
7. Follow the procedures for minor spills or proceed in accordance with authorized procedure.
8. Record the names of all persons involved in the spill. Note the details of any personal contamination.
9. If required, the radiation safety officer or person in charge will arrange for any necessary bioassay measurements.
10. If required, submit a written report to the radiation safety officer or person in charge.
11. The radiation safety officer or person in charge must notify the CNSC immediately and submit a full report within 21 days.

If an exposure may have occurred that is in excess of applicable radiation dose limits, the CNSC shall be notified **immediately** as required by section 16 of the *Radiation Protection Regulations*.

For more information, contact:

Directorate of Nuclear Substance Regulation
 Canadian Nuclear Safety Commission
 P.O. Box 1046, Station B
 Ottawa, ON K1P 5S9
 Telephone: 1-888-229-2672
 Fax: 613-995-5086

nuclearsafety.gc.ca



Canadian Nuclear
Safety Commission

Commission canadienne
de sûreté nucléaire

Canada